

- 1 -



4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.  
Mined ~~an~~ existing quarry to the eastern extent  
of the deposit. Just over 100,000 ton of ore  
was extracted - The overburden was used to  
create berms.
5. How much **additional** acreage was disturbed during the past year? 1/2
6. How much acreage was **reclaimed** during the past year? 0
7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
Began sloping areas that are "mined out" above  
highwall.
8. What is the **total** disturbed acreage of entire project at years end? 17.5
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.  
continue in same area. begin benching  
of highwall - possibly seed above Highwall

**NOTE:** Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information - R647-4-121.2 and .3

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year,** prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.


IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**


Name (Typed or Print): Tony Christoffersen  
 Title of Operator: Property - Environmental Manager  
 Signature of Operator: Tony Christoffersen  
 Date: 1-31-05



HE DAVIS  
LEVAN CHICKEN CREEK  
(West)



scale 1" = 200'



DISTURBED AREA MAP of LEVAN CHICKEN CREEK	
HE DAVIS CONSTRUCTION SPANISH FORK, UTAH	
(Acres Disturbed)	
Drawn By: Tony Christofferson	DRG. #
Date: 4/14/03	III A-1